St. Anne's college of Engineering and Technology



DEPARTMENT OF MECHANICAL ENGINEERING

ME8711 SIMULATION AND ANALYSIS LABORATORY

LABORATORY MANUAL

REGULATION - 2017

Prepared By: K.SHANMUGA ELANGO,

ASST. PROFESSOR / MECH

ME8711 SIMULATION AND ANALYSIS LABORATORY

OBJECTIVES:

To give exposure to software tools needed to analyze engineering problems. To expose the students to different applications of simulation and analysis tools.

LIST OF EXPERIMENTS

A. SIMULATION

- 1. MATLAB basics, Dealing with matrices, Graphing-Functions of one variable and two variables
- 2. Use of Matlab to solve simple problems in vibration
- 3. Mechanism Simulation using Multibody Dynamic software
- B. ANALYSIS 1. Force and Stress analysis using link elements in Trusses, cables etc.
- 2. Stress and deflection analysis in beams with different support conditions.
- 3. Stress analysis of flat plates and simple shells.
- 4. Stress analysis of axi symmetric components.
- 5. Thermal stress and heat transfer analysis of plates.
- 6. Thermal stress analysis of cylindrical shells.
- 7. Vibration analysis of spring-mass systems. 8. Model analysis of Beams.
- 9. Harmonic, transient and spectrum analysis of simple systems.

TOTAL: 60 PERIODS

OUTCOMES:

Upon the completion of this course the students will be able to CO1 simulate the working principle of air conditioning system, hydraulic and pneumatic cylinder and cam follower mechanisms using MATLAB. CO2 analyze the stresses and strains induced in plates, brackets and beams and heat transfer problems. CO3 calculate the natural frequency and mode shape analysis of 2D components and

INTRODUCTION TO FEA AND ANSYS

WHAT IS FINITE ELEMENT ANALYSIS

Finite Element Analysis, commonly called FEA, is a method of numerical analysis. FEA is used for solving problems in many engineering disciplines such as machine design, acoustics, electromagnetism, soil mechanics, fluid dynamics, and many others. In mathematical terms, FEA is a numerical technique used for solving field problems described by a set of partial differential equations.

In mechanical engineering, FEA is widely used for solving structural, vibration, and thermal problems. However, FEA is not the only available tool of numerical analysis. Other numerical methods include the Finite Difference Method, the Boundary Element Method, and the Finite Volumes Method to mention just a few. However, due to its versatility and high numerical efficiency, FEA has come to dominate the engineering analysis software market, while other methods have been relegated to niche applications. You can use FEA to analyze any shape; FEA works with different levels of geometry idealization and provides results with the desired accuracy. When implemented into modern commercial software, both FEA theory and numerical problem formulation become completely transparent to users.

WHO SHOULD USE FINITE ELEMENT ANALYSIS

As a powerful tool for engineering analysis, FEA is used to solve problems ranging from simple to very complex. Design engineers use FEA during the product development process to analyze the design-in-progress. Time constraints and limited availability of product data call for many simplifications of the analysis models. At the other end of scale, specialized analysts implement FEA to solve very advanced problems, such as vehicle crash dynamics, hydro forming, or air bag deployment. This book focuses on how design engineers use FEA as a design tool. Therefore, we first need to explain what exactly distinguishes FEA performed by design engineers from "regular" FEA. We will then highlight the most essential FEA characteristics for design engineers as opposed to those for analysts.

WHY IS FEA NEEDED

- To reduce the amount of prototype testing.
- > Computer Simulation allows multiple "what if scenarios to be tested quickly and effectively."
- To simulate designs those are not suitable for prototype testing. E.g. Surgical Implants such as an artificial knee.

ABOUT ANSYS:

ANSYS is a complete FEA software package used by engineers worldwide in virtually all fields of engineering. ANSYS is a virtual Prototyping technique used to iterate various scenarios to optimize the product.

GENERAL PROCEDURE OF FINITE ELEMENT ANALYSIS:

- > Creation of geometry or continuum using preprocessor.
- > Discretization of geometry or continuum using preprocessor.
- > Checking for convergence of elements and nodes using preprocessor.
- Applying loads and boundary conditions using preprocessor.
- > Solving or analyzing using solver
- ➤ Viewing of Results using postprocessor.

Build Geometry:

➤ Construct a two (or) three dimensional representation of the object to be modeled and tested using the work plane co-ordinate system in Ansys.

Define Material Properties:

➤ Define the necessary material from the library that composes the object model which includes thermal and mechanical properties.

Generate Mesh:

Now define how the model system should be broken down into finite pieces

Apply Loads:

> The last task in preprocessing is to restrict the system by constraining the displacement and physical loading.

Obtain Solution:

➤ The solution is obtained using solver available in ANSYS. The computer can understand easily if the problem is solved in matrices.

Present the Result:

After the solution has been obtained there are many ways to present Ansys result either in graph or in plot.

SPECIFIC CAPABILITIES OF ANALYSIS:

> Structural analysis is probably the most the common application of the finite element method such as piston, machine parts and tools.

Static Analysis:

➤ It is the used to determine displacement, stress etc. under static loading conditions. Ansys can compute linear and non-linear types (e.g. the large strain hyper elasticity and creep problems)

Transient Dynamic Analysis:

➤ It is used to determine the response of a structure to time varying loads.

Buckling Analysis:

➤ It is used to calculate buckling load and to determine the shape of the component after applying the buckling load. Both linear buckling and non – linear buckling analysis are possible.

Thermal Analysis:

- The steady state analysis of any solid under thermal boundary conditions calculates the effect of steady thermal load on a system (or) component that includes the following.
- a) Convection.
- b) Radiation.
- c) Heat flow rates.
- d) Heat fluxes.
- e) Heat generation rates.
- f) Constant temperature boundaries.

Fluid Flow:

The ANSYS CFD offers comprehensive tools for analysis of two-dimensional and three dimensional fluid flow fields.

Magnetic:

Magnetic analysis is done using Ansys / Electromagnetic program. It can calculate the magnetic field in device such as power generators, electric motor etc. Interest in magnetic analysis is finding magnetic flux, magnetic density, power loss and magnetic forces.

Acoustic / Vibrations:

- Ansys is the capable of modeling and analyzing vibration system. Acoustic is the study of the generation, absorption and reflection of pressure waves in a fluid application.
- Few examples of acoustic applications are
- a) Design of concert house, where an even distribution of sound pressure is possible.

- b) Noise cancellation in automobile.
- c) Underground water acoustics.
- d) Noise minimization in machine shop.
- e) Geophysical exploration.

Coupled Fields:

A coupled field analysis is an analysis that takes into account the iteration between two (or) more fields of engineering analysis. Pressure vessels, Induction heating and Micro electro mechanical systems are few examples


RESULT:

Thus the basics of FEA and ANSYS are studied.

1. TRUSS ANALYSIS

Ex: No: 1

AIM: To determine the nodal deflections, reaction forces, and stress for the truss system shown below (E = 200GPa, $A = 3250mm^2$).



Analytical Solution:

 Σ H=0 (sum of the horizontal force is equal to zero)

 $\Sigma v=0$ (sum of the vertical force is equal to zero)

 Σ M=0 (sum of the moment force is equal to zero)

 Σ Moment=0

 $0 \text{=-}210 \times 3.6 \text{--}280 \times 7.2 \text{ --}360 \times 10.8 \text{+-} R_2 \times 10.8$

 $R_2 = 616.66 \text{ kN}$


 $\Sigma v=0$

 $=280-210-280-360+617+R_1=0$

 $R_1 = 513 \text{ kN}$

Node 7

Consider the force is away from the joints.



 $\Sigma v=0$

 $-360+616+F_{11} \sin 60^{\circ}=0$

 F_{11} =-296.3

$$\sigma_{11} = \frac{-296.3}{3250} = -91.8 \, MPa$$

 $\Sigma H=0$

 $F_{10}+F_{11}=\cos 60^{\circ}=0$


 F_{10} =- $F_{11} \cos 60^{\circ}$

 F_{10} =- 296.3×cos60°

 F_{10} =- 148.15

$$\sigma_{10} = \frac{-148.15}{3250} = -45.58 \, MPa$$

Node 5



 $\Sigma v=0$

$$-280+-296.3 \sin 60^{\circ}+F_7 \sin 60^{\circ}=0$$

$$F_7 = \frac{23.3}{\sin 60^\circ} = 27.016$$

$$\sigma_7 = \frac{27.016}{3250} = 8.312 \ \textit{MPa}$$

 $\Sigma H=0$

148.15- F_6 + $296.3 \cos 60^{\circ}$ +27.016

 $\cos 120^{\circ} = 0$

 $148.15+134.642=F_6$

 $F_6 = 282.792$

$$\sigma_6 = \frac{282.792}{3250} = 87.012 \, MPa$$

ANSYS Analysis Procedure:

- Utility menu bar: select File > Change Title:
 Enter the title (Give title of your choice) in the window appeared and Click 'OK'.
- 2. ANSYS Main Menu: Preferences > Structural > Click 'OK'
- 3. ANSYS Main Menu: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>select Link (sub window 1)> 2d spar (sub window 2)> Click 'OK'
- 4. **ANSYS Main Menu: Preprocessor>Real Constants > Add/Edit/Delete>** Click **Add...** and select 'LINK1'> Click on 'OK'. The **Real Constants** window will appear> input **AREA** = 3250>Click on 'OK'. 'Set 1' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window.
- 5. ANSYS Main Menu: Preprocessor>Material Props > Material Models>Structural>Linear>Elastic>Isotropic>in the Linear elastic isotropic material model window, input E=200000 and Poisson's ratio=0.3
- 6. ANSYS Main Menu: Preprocessor > Modeling > Create > Keypoints > In Active CS, in the create key points in active coordinate system, type key point no. and its coordinates. Here
 - KP x y z From the problem figure, calculate the key point values

```
1
      0
            0
                   0 (Click 'apply')
2
   1800 3118
                   0 (Click 'apply')
                   0 (Click 'apply')
3
   3600
             0
4
   5400 3118
                    0 (Click 'apply')
   7200
                   0 (Click 'apply')
             0
                   0 (Click 'apply')
  9000 3118
7 10800
                   0 (Click 'ok')
             0
```

- 7. In the Command window bar, type:
 - L,1,2 (enter) L,1,3 (enter) L,2,3 (enter) L,2,4 (enter) L,3,4 (enter) L,4,5 (enter) L,5,6 (enter) L,4,6 (enter) L,6,7 (enter) L,5,7 (enter)
- 8. ANSYS Main Menu: Preprocessor>Meshing > Size Cntrls> Manual Size> Lines > All Lines, in the Element sizes on All selected Lines window, input in the 'NDIV' No. of divisions field = 1. Click 'OK'
- 9. **ANSYS Main Menu: Preprocessor>Meshing > Mesh > Lines**, Click 'Pick All' in the 'Mesh Lines' Window.
- 10. ANSYS Main Menu: Solution > select Analysis Type > New Analysis > Tick Static, Click 'OK'
- 11. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > On Key points, Type key point 1,7 in the Apply U, ROT on KPs window click 'OK', then select 'All dof' in the Apply U, ROT on KPs window (Check Apply as field with 'Constant value' and VALUE = 0), then Click 'OK'
- 12. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Force/Moment > on Key points, Type key point 3 in the Apply F/M on KPs window click 'OK', in the Apply F/M on KPs window, set Direction of force field as FY, Apply as field as Constant and VALUE = -280000, then Click 'OK'
- 13. Similarly, Apply loads in the Key points 1, 5, and 7 with load -210000, -280000 and -360000 respectively.
- 14. ANSYS Main Menu: Solution >Solve > Current LS> Click Solve.
- 15. Click 'Close' in Solution is Done window.
- 16. ANSYS Main Menu: General Postproc> List Results > Reaction Solution, in the List Reaction Solution window, select 'All Struc force F', Click 'OK'.
- 17. Print Solution window will show the Reaction results.
- 18. ANSYS Main Menu: General Postproc> Plot Results > Deformed Shape, in the Plot Deformed shape window, Tick deformed + undeformed edge (shows the deformed shape of the structure in the ANSYS main window).
- 19. ANSYS Main Menu: General Postproc> Plot results > Contour Plot > Nodal Solution, in the Contour Nodal Solution Data, click DOF solution > Displacement vector sum, Click 'OK'. (Shows the displacement contour of deformed structure in the ANSYS main window).
- 20. ANSYS Main Menu: General Postproc> Element Table > Define Table, in the Element table data window, Click 'ADD'.
- 21. In the Additional Element table items window, in the User defined label field, type 'SAXL', and select 'By sequence numb' in the Item, Comp Results data item field (sub window1) and 'LS' (sub window2), then type 'LS, 1' in the field below the sub window2 and Click 'OK'.
- 22. ANSYS Main Menu: General Postproc> Element Table > Plot Elem Table, in the Item to be plotted field, select 'SAXL' and click 'OK'. (Shows the Axial load contour of deformed structure in the ANSYS main window).
- 23. ANSYS Main Menu: General Postproc> Element Table > List Element Table.
- 24. Print Solution window will show the Axial load results on each element.

MERITS:1.time saved

2.achived high accuracy.

APPLICATIONS: Beams are structural members, which are most commonly used in buildings. Beams have numerous other applications in case of bridges, automobiles or in mechanical systems. In this article we will see how we can do strength analysis of a beam

RESULT:

Thus the performance of nodal deflections, reaction forces, and stress for the truss system was analyzed and animated

Ex: No: 2 STRESS ANALYSIS OF PLATE WITH CIRCULAR HOLE AIM:

To determine the stress acting on a plate with circular hole due to the applied external pressure. **SOFTWARE REQUIRED**:

Ansys 14.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok.
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow solid \rightarrow quad 4 node 182 \rightarrow ok.

Option \rightarrow k1-full integration \rightarrow k2-plane stress \rightarrow k3-pure displacement \rightarrow ok \rightarrow close.

- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close.
- 4. Modeling \rightarrow create \rightarrow area \rightarrow rectangle \rightarrow by 2 corners \rightarrow (enter the following values on the boxes) X = 0; Y = 0; width = 100 height $= 100 \rightarrow$ ok.
- 5. Work plane \rightarrow off set wp to \rightarrow key points $+ \rightarrow$ (select the two opposite corners of solid rectangle) \rightarrow ok \rightarrow (now axis move to centre of rectangle).

Create \rightarrow solid circle \rightarrow radius (10) \rightarrow ok. (Small circle generated)

- 6. Operate \rightarrow Booleans \rightarrow subtract \rightarrow area \rightarrow (select larger area) \rightarrow ok \rightarrow ok (select smaller area) \rightarrow next \rightarrow ok \rightarrow ok. (now hole is generated on the solid rectangle)
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set size (3) \rightarrow ok \rightarrow mesh \rightarrow (select the area) \rightarrow ok
- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on lines \rightarrow (select the line) \rightarrow ok \rightarrow ALL DOF \rightarrow ok.
- 9. Pressure \rightarrow on lines \rightarrow (select the line) \rightarrow ok. Load value \rightarrow (-500) \rightarrow ok.

(To see the number of pressure lines do the following procedure). Plot control \rightarrow symbols \rightarrow show pressures \rightarrow arrows \rightarrow ok. (Next move to) Plot \rightarrow multi plot \rightarrow type SBCT \rightarrow (press enter)

- 11. General post processor \rightarrow plot result \rightarrow counter plot \rightarrow nodal solution \rightarrow structural \rightarrow Stress (or) Displacement sum \rightarrow von misses stress (or) U sum \rightarrow ok.
- 12. Plot control \rightarrow animates \rightarrow deformation results \rightarrow stress (or) displacement sum \rightarrow von misses stress (or) U sum \rightarrow ok

MERITS: 1.time saved 2.achived high accuracy.

APPLICATIONS: Geometric irregularities such as holes, notches, keyways, shoulders provided on shafts etc. are common features provided in machine members. But such irregularities often lead to stress concentration near the irregularity due to which the stress near the irregularity is higher than the average stress in the whole member

RESULT:

Thus the performance of the stress analysis of a plate with a circular hole was analyzed and animated.

Ex: No: 4 STRESS ANALYSIS OF AXI – SYMMETRIC COMPONENT AIM:

To determine the stress analysis on a axi symmetric component.

SOFTWARE REQUIRED:

Ansys 14.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow solid \rightarrow quad 4 node 182 \rightarrow ok.

Option \rightarrow k1- full integration \rightarrow k2 – plane stress k3 – axis symmetric \rightarrow ok \rightarrow close.

- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) PX = 2.1e4 and PRXY = 0.3 \rightarrow ok \rightarrow close. And then select \rightarrow density (type the value) 7.85e-6 \rightarrow ok \rightarrow close.
- 4. Modeling \rightarrow create \rightarrow area \rightarrow rectangle \rightarrow by 2 corners \rightarrow (enter the following values on the boxes) \rightarrow X = 500; Y = 0; width = 50 height = 100 \rightarrow ok.
- 5. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set size (5) \rightarrow ok \rightarrow mesh \rightarrow (select the area) \rightarrow ok
- 6. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on lines \rightarrow (select the bottom line of the rectangle) \rightarrow ok \rightarrow UY \rightarrow ok.
- 7. Inertia \rightarrow angular velocity \rightarrow global \rightarrow Y = (2*3.14*3000)/60 (ie $\omega = 2\pi N/60$) \rightarrow ok
- 8. Solve \rightarrow current LS \rightarrow ok
- 9. General post processor \rightarrow plot result \rightarrow counter plot \rightarrow nodal solution \rightarrow stress (or) displacement sum \rightarrow von misses stress (or) U sum \rightarrow ok
- 10. Plot control \rightarrow animates \rightarrow deformation results \rightarrow stress (or) displacement sum \rightarrow von misses stress (or) U sum \rightarrow ok.

RESULT:

Thus the stress distribution of axi symmetric component is analyzed ,animated and plotted.

Ex: No: 5 (a) STRESS ANALYSIS OF BEAM

(Cantilever Beam)

AIM:

To determine the stress acting on a cantilever beam due to the applied external load.

SOFTWARE REQUIRED:

Ansys 10.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok.
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) \rightarrow PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close.
- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 100; height = 100 \rightarrow ok.
- 5. Modeling \rightarrow create \rightarrow key points \rightarrow In active CS

 $1 \text{st } 0 \ 0 \ 0 \rightarrow \text{apply}$ $2 \text{nd } 1000 \ 0 \ 0 \rightarrow \text{ok}$

(1st) & (2nd) Key points Generated.

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line select 1 st and 2nd point \rightarrow ok
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set size (10) \rightarrow ok \rightarrow mesh \rightarrow select the line \rightarrow ok
- 8. Solution \rightarrow define \rightarrow load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points (select the 1_{st} point) \rightarrow ok \rightarrow All DOF \rightarrow ok.
- 9. Force \rightarrow key points \rightarrow (select the point where we apply the load) \rightarrow FY (- 500) \rightarrow ok.
- 10. Solve \rightarrow current LS \rightarrow ok.
- 11. General post processor \rightarrow plot result \rightarrow counter plot \rightarrow nodal solution \rightarrow structural \rightarrow stress \rightarrow von misses stress \rightarrow ok.
- 12. Plot control \rightarrow animates \rightarrow deformation results \rightarrow stress \rightarrow von misses stress \rightarrow ok.
- 13. Element table \rightarrow Add \rightarrow Select Sum Sequence all \rightarrow Type 6, Apply, Select sum sequence all \rightarrow Type 19, Apply Select sum sequence all \rightarrow Type 2, Apply, Select sum sequence all, Type 15 \rightarrow ok.

14. Plot result \rightarrow counter polt \rightarrow Line element result \rightarrow select 6,19 to get shear force diagram, select 2,15 to get Bending moment diagram.

RESULT:

Thus the performance of the stress analysis of a cantilever beam was analyzed, animated, shear force and bending moment diagram was plotted

Ex: No: 5 (b) STRESS ANALYSIS OF BEAM

(Simply Supported Beam)

AIM:

To determine the stress acting on a simply supported beam due to the applied external load.

SOFTWARE REQUIRED:

Ansys 10.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok \rightarrow close.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close.
- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 100; height = 100 \rightarrow ok.
- 5. Modeling \rightarrow create \rightarrow key points \rightarrow In active CS

 $1st 0 0 0 \rightarrow apply$

 $2nd\ 1000\ 0\ 0 \rightarrow ok$

(1st) & (2nd) Key points Generated.

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line \rightarrow select 1st and 2nd point \rightarrow ok.
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set size (10) \rightarrow ok \rightarrow mesh select the line \rightarrow ok.
- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points (select the 1_{st} and 2_{nd} key points) \rightarrow ok \rightarrow UY & ROT UY \rightarrow ok.
- 9. Force \rightarrow node \rightarrow (select the node where we apply the load) \rightarrow FY (-500) \rightarrow ok.
- 10. Solve \rightarrow current LS \rightarrow ok.
- 11. General post processor \rightarrow plot result \rightarrow counter plot \rightarrow nodal solution \rightarrow structural \rightarrow stress \rightarrow von misses stress \rightarrow ok.
- 12. Plot control \rightarrow animates \rightarrow deformation results \rightarrow stress \rightarrow von misses stress \rightarrow ok.

- 13. Element table \rightarrow Add \rightarrow Select Sum Sequence all \rightarrow Type 6, Apply, Select sum sequence all \rightarrow Type 19, Apply Select sum sequence all \rightarrow Type 2, Apply, Select sum sequence all, Type 15 \rightarrow ok.
- 14. Plot result \rightarrow counter polt \rightarrow Line element result \rightarrow select 6,19 to get shear force diagram, select 2,15 to get Bending moment diagram.

RESULT:

Thus the performance of the stress analysis of a simply supported beam was analyzed, animated, shear force and bending moment diagram was plotted.

Ex: No: 5(c) STRESS ANALYSIS OF BEAM

(Fixed Beam)

AIM:

To determine the stress acting on a fixed beam due to the applied external load.

SOFTWARE REQUIRED:

Ansys 10.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok.
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok \rightarrow close.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic isotropic \rightarrow (enter the following values on the boxes) \rightarrow PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close.
- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 100; height = 100 \rightarrow ok.
- 5. Modeling \rightarrow create \rightarrow key points \rightarrow in active \rightarrow CS

 $1_{st} \ 0 \ 0 \ 0 \rightarrow apply$ $2_{nd} \ 1000 \ 0 \ 0 \rightarrow ok$ $(1_{st}) \ \& \ (2_{nd}) \ key \ points \ Generated.$

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line \rightarrow select 1_{st} and 2_{nd} point \rightarrow ok
- 7. Meshing \rightarrow mesh tool \rightarrow global set \rightarrow size (10) \rightarrow ok \rightarrow mesh \rightarrow select the line \rightarrow ok.

- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points (select the 1_{st} and 2_{nd} key points) \rightarrow ok \rightarrow All DOF \rightarrow ok.
- 9. Force \rightarrow node \rightarrow (select the node where we apply the load) \rightarrow FY (-500) \rightarrow ok.
- 10. Solve \rightarrow current LS \rightarrow ok.
- 11. General post processor \rightarrow plot result \rightarrow counter plot \rightarrow nodal solution \rightarrow structural \rightarrow stress \rightarrow von misses stress \rightarrow ok.
- 12. Plot control \rightarrow animates \rightarrow deformation results \rightarrow stress \rightarrow von misses stress \rightarrow ok.
- 13. Element table \rightarrow Add \rightarrow Select Sum Sequence all \rightarrow Type 6, Apply, Select sum sequence all \rightarrow Type 19, Apply Select sum sequence all \rightarrow Type 2, Apply, Select sum sequence all, Type 15 \rightarrow ok.
- 14. Plot result \rightarrow counter polt \rightarrow Line element result \rightarrow select 6,19 to get shear force diagram, select 2,15 to get Bending moment diagram.

MERITS: 1.time saved 2.achived high accuracy.

APPLICATIONS: dynamic analysis of machine elements

RESULT:

Thus the performance of the stress analysis of a simply supported beam was analyzed, animated, shear force and bending moment diagram was plotted.

Ex: No: 6(a) MODE FREQUENCY ANALYSIS OF BEAMS (Cantilever Beam)

AIM:

To determine the stress due to mode frequencies on a cantilever beam due to the applied external load.

SOFTWARE REQUIRED:

Ansys 14.0

PROCEDURE:

1. Preferences \rightarrow structural \rightarrow ok.

- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok \rightarrow close.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isentropic \rightarrow (enter the following values on the boxes) \rightarrow PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close and then select density (type the value) \rightarrow 7850e-12 \rightarrow ok \rightarrow close.
- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 10; height = 10 \rightarrow ok.
- 5. Modeling \rightarrow create \rightarrow key points \rightarrow In active CS

```
1_{st} 0 0 0 \rightarrow apply

2_{nd} 1000 0 0 \rightarrow ok

(1_{st}) \& (2_{nd}) key points Generated.
```

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line \rightarrow select 1_{st} and 2_{nd} point \rightarrow ok
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set size (10) \rightarrow ok \rightarrow mesh \rightarrow select the line \rightarrow ok.
- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points \rightarrow (select the 1_{st} point) \rightarrow ok \rightarrow All DOF \rightarrow ok.
- 9. Solution \rightarrow analysis type \rightarrow new analysis \rightarrow modal \rightarrow ok.
- 10. Analysis option \rightarrow (enter the following value) \rightarrow exact = 10 expand = 10 \rightarrow ok \rightarrow default \rightarrow ok.
- 11. Solve \rightarrow current LS \rightarrow ok
- 12. General post processor \rightarrow read result \rightarrow by pick (from the set-frequency table) \rightarrow close
- 13. Read result \rightarrow first set \rightarrow plot result \rightarrow contour plot \rightarrow nodal solution \rightarrow DOF solution \rightarrow displacement vector sum \rightarrow ok
- 14. Read result \rightarrow next set \rightarrow (right click on the screen \rightarrow replot (difference mode will come on the screen)
- 15. Plot control \rightarrow animates \rightarrow mode shape \rightarrow DOF solution \rightarrow ok.

RESULT:

Thus the performance of the mode frequencies on a cantilever beam was analyzed and animated.

Ex.No.6 (b) MODE FREQUENCY ANALYSIS OF BEAMS (Simply Supported Beam)

AIM:

To determine the stress due to mode frequencies on a simply supported beam due to the applied external load.

SOFTWARE REQUIRED:

Ansys 14.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok.
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok \rightarrow close.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) \rightarrow PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close. and then select \rightarrow density (type the value) \rightarrow 7850e-12 \rightarrow ok \rightarrow close.
- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 10; height = 10 \rightarrow ok.
- 5. modeling \rightarrow create \rightarrow key points \rightarrow in active \rightarrow CS

 $1_{st} \ 0 \ 0 \ \rightarrow apply$ $2_{nd} \ 1000 \ 0 \ \rightarrow ok$ $(1_{st}) \ \& \ (2_{nd}) \ key \ points \ Generated.$

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line \rightarrow select 1st and 2nd point \rightarrow ok.
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set \rightarrow size (10) \rightarrow ok \rightarrow mesh select the line \rightarrow ok.
- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points \rightarrow (select the 1st and 2nd key points) \rightarrow ok \rightarrow UY & ROT UY \rightarrow ok.
- 9. Solution \rightarrow analysis type \rightarrow new analysis \rightarrow modal \rightarrow ok.
- 10. Analysis option (enter the following value) \rightarrow exact = 10 expand = 10 \rightarrow ok \rightarrow default \rightarrow ok
- 11. Solve \rightarrow current LS \rightarrow ok.

- 12. General post processor \rightarrow read result \rightarrow by pick \rightarrow (from the set-frequency table) \rightarrow close.
- 13. Read result \rightarrow first set \rightarrow plot result \rightarrow contour plot \rightarrow nodal solution \rightarrow DOF solution \rightarrow displacement vector sum \rightarrow ok
- 14. Read result \rightarrow next set \rightarrow (right click on the screen \rightarrow replot (difference mode will come on the screen)
- 15. Plot control \rightarrow animates \rightarrow mode shape \rightarrow DOF solution \rightarrow Displacement vector sum \rightarrow ok.

RESULT:

Thus the performance of the mode frequencies on a simply supported beam was analyzed and animated.

Ex.No.6(c) MODE FREQUENCY ANALYSIS OF BEAMS (Fixed Beam)

AIM:

To determine the stress due to mode frequencies on a fixed beam due to the applied external load. **SOFTWARE REQUIRED**:

Ansys 14.0

PROCEDURE:

- 1. Preferences \rightarrow structural \rightarrow ok.
- 2. Preprocessor \rightarrow element type \rightarrow add \rightarrow add \rightarrow beam \rightarrow 2 node 188 \rightarrow ok \rightarrow close.
- 3. Material property \rightarrow material models \rightarrow structure \rightarrow linear \rightarrow elastic \rightarrow isotropic \rightarrow (enter the following values on the boxes) \rightarrow PX = 2e5 and PRXY = 0.3 \rightarrow ok \rightarrow close. and then select \rightarrow density (type the value) \rightarrow 7850e-12 \rightarrow ok \rightarrow close.

- 4. Sections \rightarrow beam \rightarrow common section \rightarrow width = 10; height = 10 \rightarrow ok.
- 5. Modeling \rightarrow create \rightarrow key points \rightarrow In active CS

 $1 \text{st } 0 \ 0 \ 0 \rightarrow \text{apply}$

 $2nd\ 1000\ 0\ 0 \rightarrow ok$

(1st) & (2nd) Key points Generated.

- 6. Modeling \rightarrow Create \rightarrow line \rightarrow straight line \rightarrow select 1_{st} and 2_{nd} point \rightarrow ok.
- 7. Meshing \rightarrow mesh tool \rightarrow global \rightarrow set \rightarrow size (10) \rightarrow ok \rightarrow mesh select the line \rightarrow ok.
- 8. Solution \rightarrow define load \rightarrow apply \rightarrow structural \rightarrow displacement \rightarrow on key points \rightarrow (select the 1st and 2nd key points) \rightarrow ok \rightarrow All DOF \rightarrow ok
- 9. Solution \rightarrow analysis type \rightarrow new analysis \rightarrow modal \rightarrow ok
- 10. Analysis option \rightarrow (enter the following value) \rightarrow exact = 10 expand = 10 \rightarrow ok \rightarrow default \rightarrow ok
- 11. Solve \rightarrow current LS \rightarrow ok
- 12. General post processor \rightarrow read result \rightarrow by pick (from the set-frequency table) \rightarrow close
- 13. Read result \rightarrow first set \rightarrow plot result \rightarrow contour plot \rightarrow nodal solution \rightarrow DOF solution \rightarrow displacement vector sum \rightarrow ok
- 14. Read result \rightarrow next set \rightarrow (right click on the screen \rightarrow replot (difference mode will come on the screen)
- 15. Plot control \rightarrow animates \rightarrow mode shape \rightarrow DOF solution \rightarrow Displacement vector sum \rightarrow ok.

MERITS: 1.time saved

2.achived high accuracy.

APPLICATIONS: dynamic analysis of machine elements

RESULT:

Thus the performance of the mode frequencies on a fixed beam was analyzed and animated.

Ex: No: 7 HARMONIC ANALYSIS OF A 2D COMPONENT

AIM:

To determine the Harmonic response of a 2D component

SOFTWARE:

Ansys 10.0

PROCEDURE:

- 1. Start \rightarrow Program \rightarrow Ansys \rightarrow Ansys product launcher
- 2. Preference \rightarrow Structural \rightarrow OK
- 3. Preprocessor \rightarrow Element Type \rightarrow Add \rightarrow Add \rightarrow Beam \rightarrow 2 node 188 \rightarrow Ok
- 4. Material Properties \rightarrow Material Model \rightarrow Structural \rightarrow Linear \rightarrow Elastic \rightarrow Isontropic \rightarrow E = 2e5, $\gamma = 0.3 \rightarrow Ok \rightarrow Density = 7860e-12 \rightarrow Ok$
- 5. Section \rightarrow Beam \rightarrow Common Section \rightarrow width = 10, Height = 10 \rightarrow Ok
- 6. Modelling \rightarrow Create \rightarrow Keypoints \rightarrow In Active CS \rightarrow X1 = 0, Y1 = 0, Z1 = 0 \rightarrow Apply \rightarrow X2 = 1000, Y2 = 0, Z = 0 \rightarrow Ok
- 7. Modelling \rightarrow create \rightarrow Line \rightarrow Lines \rightarrow Straight Line \rightarrow Select the two points \rightarrow Ok
- 8. Meshing \rightarrow Mesh Tool \rightarrow Global, Set \rightarrow Element type = $10 \rightarrow$ Ok \rightarrow Mesh \rightarrow Select the Line \rightarrow Ok
- 9. Solution \rightarrow Analysis Type \rightarrow New Analysis \rightarrow Harmonic \rightarrow Ok
- 10. Solution \rightarrow Define Load \rightarrow Apply \rightarrow Structural \rightarrow Displacement \rightarrow on key points \rightarrow Select 1st key point \rightarrow Ok \rightarrow ALL DOF \rightarrow Ok
- 11. Solution \rightarrow Define Load \rightarrow Apply \rightarrow Structural \rightarrow Force \rightarrow on Key points \rightarrow Select 2nd key points \rightarrow Y= -100 \rightarrow Ok
- 12. Solution \rightarrow Load step opts \rightarrow Time and Frequency \rightarrow Frequency and substeps \rightarrow Harmonic Frequency range = 0, 100; No of substep = $100 \rightarrow \text{Ok}$
- 13. Solve \rightarrow Current LS \rightarrow Ok
- 14. Time Hist Postprocessor → Add Data → DOF → Y Displacement → Ok Select the Maximum deflection point → Ok

 At Top slick Creek Data → Posselt sources for without descripe and dition
- At Top click Graph Data → Result comes for without damping condition
- 15. Solution \rightarrow Load Step opts \rightarrow Time and Frequency \rightarrow Frequency and substeps \rightarrow Harmonic Frequency range = 0, 100; Substep = $100 \rightarrow Ok$ Damping \rightarrow Constant Damping ratio $\rightarrow 0.1 \rightarrow Ok$

16. Solve \rightarrow Current LS \rightarrow Ok

17. Time Hist Postprocessor \rightarrow Add Data \rightarrow DOF \rightarrow Y Displacement \rightarrow Ok

Select the maximum Deflection point \rightarrow Ok

At Top Click Graph Data → Result comes for with Damping condition

MERITS: 1.time saved 2. Achived high accuracy.

APPLICATIONS: Vibration, mechanical and acoustic measurements — Material testing and measurements with in-house testing stand

RESULT:

Thus the Harmonic response of the 2D component has been analyzed and animated.


Ex: No: 9. TRANSIENT ANALYSIS OF A SPRING MASS DAMPER SYSTEM USING ANSYS

AIM:

To determine the transient analysis of a spring mass damper system by using ansys

SOFTWARE:

Ansys 10.0



Problem:

Show the effect of damper and its damped oscillation when the mass m is displaced from its equilibrium position and left free for its damped oscillation (as shown in Fig.7). Take spring stiffness (K)

= 100 N/m, and mass (m) = 10 kg. Show the response of the following cases, when damping coefficient (i) C = 0, (ii) C = 0.1 of C_c (iii) $C = C_c$, (iv) C = 1.2 of C_c where $C_c =$ critical damping coefficient = $2\sqrt{K*m}$

ANSYS Analysis Procedure:

COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty, COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14> click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes> In Active CS, in the create node: active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling> Create>Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click Apply) 2 1 0 0 (Click Apply) 3 1 0 0 (Click Apply) 4 2 1 0 0 (Click Apply) 5 2 1 0 0 (Click Apply) 5 3 ANSYS Main Menu: Preprocessor>Modeling> Create> Element> Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK' 8 3 4 ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > nodes> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9 4 ANSYS Main Menu: Solution > Define Loads > Apply > Initial Condition> Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1' Click '		,			
 Main menu bar: Preferences > Structural> Click 'OK' Main menu bar: Preprocessor> Element Type > Add/Edit/Delete > in the window click Add>select combination(sub window 1)> spring damper14(sub window 2)> Click 'OK' Main menu bar: Preprocessor> Element Type > Add/Edit/Delete > in the window select "ty COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor> Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)> 3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor> Element Type > Add/Edit/Delete > in the window select "ty COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' Main menu bar: Preprocessor>Real Constants window will appear> input K = 100> CV1=10> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window active coordinate system, type key point no. and its coordinates. Here node: a y z 1 0 0 0 (Click 'OK') ANSYS Main Menu: Preprocessor> Modeling> Create> nodes> In Active CS> in the create node: a ctive coordinate system, type key point no. and its coordinates. Here node: x y z 1 0 0 0 (Click 'OK') ANSYS Main Menu: Preprocessor> Modeling> Create> Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number x y Z 1 0 0 0 (Click OK) ANSYS Main Menu: Preprocessor> Modeling> Create> Element> Auto Numbered> Thron Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cooks> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' ANSYS Main Menu: So	1.	·			
 Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>select combination(sub window 1)> spring damper14(sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type COMBIN14> click on "OPTIONS" > K3 options (select) 2-D w/o rot iner> click 'OK' Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete > lin the window select "type COMBIN14'> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Select Mass21'> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the "Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes In Active CS, in the create node active coordinate system, type key point no. and its coordinates. Here node active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 (Click 'OK') ANSYS Main Menu: Preprocessor>Modeling> Create> Nodes In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 (Click OK) ANSYS Main Menu: Preprocessor> Modeling> Create> Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and CyoK'> (OK'> (Enter) and CyoK'> (Enter) and CyoK'>		**			
Add>select combination(sub window 1)> spring damper14(sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14> Click on 'OK'. The Real Constants window will appear> input K = 100> CV1=10> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window 5. Main menu bar: Preprocessor>Modeling> Create > nodes> In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling> Create>Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 0 (Click Apply) 2 1 1 0 0 0 (Click Apply) 3 ANSYS Main Menu: Preprocessor>Modeling> Create> Element> Auto Numbered> Thro Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > nodes> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution > Define Loads > Apply > Initial Condition> Define> In the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select					
Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty, COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty, COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select	3.	Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click			
COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty, COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4.		Add>select combination(sub window 1)> spring damper14(sub window 2)> Click 'OK'			
Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14> click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. Set 1' now appears in the dialog box. Select Mass21'> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes > In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling> Create>Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling> Create> Element> Auto Numbered> Thronomy Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > nodes> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution > Define Loads > Apply > Initial Condition> Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'. Click 'OK'. 10. ANSYS Main Menu: Solution > Analysis Type> Sol'n controls > Transient> Click 'OK' Click 'OK'. 11. ANSYS Main Menu: Solution > Analysis Type> Sol'n controls > Transient> Click 'OK' Click 'OK'.		Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type1"			
Add>selectstureutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK' Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. Set 1' now appears in the dialog box. Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes		COMBIN14> click on "OPTIONS" > K2 options (enter) longitude UY DOF			
 Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "ty COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. Set 1' now appears in the dialog box. Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'GK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Thron Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply > Initial Condition>Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type> New Analysis>Transient>Click 'OK'-Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>Click 'OK'-Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>click 'OK'-Click 'OK'-		Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window click			
COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK' 4. Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14'> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. Set 1' now appears in the dialog box. Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window 5. Main menu bar: Preprocessor>Modeling> Create > nodes> In Active CS, in the create node: active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling> Create>Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling> Create> Element> Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > nodes> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution > Define Loads > Apply > Initial Condition> Define loads > Apply > Initial Condition> Define loads > Apply '. Then in the Define linitial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'. Click 'OK'. 10. ANSYS Main Menu: Solution > Analysis Type> New Analysis> Transient> Click 'OK' Click 'OK'. 11. ANSYS Main Menu: Solution > Analysis Type> Sol'n controls > Transient> Click 'OK' Click 'OK'.		Add>selectsturcutral mass(sub window 1)>3D mass 21 (sub window 2)> Click 'OK'			
 Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select 'COMBIN14'> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. The Real Constants window will appear> input Mass = 10 Click on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Click on 'OK'. Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes > In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node		Main menu bar: Preprocessor>Element Type > Add/Edit/Delete > in the window select "type1"			
 'COMBIN14'> Click on 'OK'. The Real Constants window will appear> input K = 100>CV1=10> Click on 'OK'. Set 1' now appears in the dialog box. Select Mass21'> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create > nodes > In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling> Create>Nodes> In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling> Create> Element> Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > nodes> Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution > Define Loads > Apply > Initial Condition> Define in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'. Click 'OK'. 10. ANSYS Main Menu: Solution > Analysis Type> New Analysis Transient> In the Full Transient Options Tick Transient effects and in the Algorithm Field> select HHT algorithm. 		COMBIN14> click on "OPTIONS" > K3options (select) 2-D w/o rot iner> click 'OK'			
100>CV1=10> Click on 'OK'. 'Set 1' now appears in the dialog box. Select Mass21'> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window Main menu bar: Preprocessor>Modeling> Create >nodes> In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 0 (Click Apply) 2 1 0 0 0 (Click Apply) 2 1 0 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Co'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	4.	Main menu bar: Preprocessor>Real Constants > Add/Edit/Delete> Click Add and select			
Select Mass21> Click on 'OK'. The Real Constants window will appear> input mass = 10 Clic on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window 5. Main menu bar: Preprocessor>Modeling> Create >nodes> In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Thro Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.		'COMBIN14'> Click on 'OK'. The Real Constants window will appear> input K =			
on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window 5.		100>CV1=10> Click on 'OK'. 'Set 1' now appears in the dialog box.			
 5. Main menu bar: Preprocessor>Modeling> Create >nodes> In Active CS, in the create nodes active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Coordinates of the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Coordinates of the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Coordinates of the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Coordinates of the Elements of the Elements from Nodes window that the Element in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 		Select Mass21'> Click on 'OK'. The Real Constants window will appear> input mass = 10 Click			
active coordinate system, type key point no. and its coordinates. Here node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 0 (Click Apply) 2 1 0 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Thro Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.		on 'OK'. 'Set 2' now appears in the dialog box. Click on 'Close' in the 'Real Constants' window			
node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply > Initial Condition>Define>in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	5.	Main menu bar: Preprocessor>Modeling> Create >nodes> In Active CS, in the create nodes in			
node x y z 1 0 0 0 (Click 'apply') 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply > Initial Condition>Define>in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.		active coordinate system, type key point no. and its coordinates. Here			
 2 0 -1 0 (Click 'OK') 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply > Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 					
 6. ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 		1 0 0 (Click 'apply')			
following in the Create Nodes in the Active Coordinate System window Node number X Y Z 1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.		2 0 -1 0 (Click 'OK')			
Node number X Y Z 1 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Thrown Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	6.	ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS> type the			
1 0 0 0 (Click Apply) 2 1 0 0 (Click OK) 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Thrown Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.		following in the Create Nodes in the Active Coordinate System window			
 7. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Creok'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 					
 ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Auto Numbered> Throw Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and Cook'. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 					
 Nodes, in the Elements from Nodes window, type '1' (Enter) and type '2' (Enter) and C. 'OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 	7				
 *OK'. 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with ' Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 	7.	_			
 8. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement > nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 					
 Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = then Click 'OK' 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 	8.	ANSYS Main Menu: Solution > Define Loads > Apply > Structural > Displacement > On			
 then Click 'OK' ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 		nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'UX' in the			
 9. ANSYS Main Menu: Solution >Define Loads > Apply >Initial Condition>Define>in the Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 		Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and $VALUE = 0$),			
Define Initial Conditions window type '2' and Click 'Apply'. Then in the Define Initial Conditions window, in the DOF to be specified field select 'UX'and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.					
Conditions window, in the DOF to be specified field select 'UX' and in the Initial value of DOF type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	9.				
type '-1'.Click 'OK'. 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.					
 10. ANSYS Main Menu: Solution >Analysis Type>New Analysis>Transient>Click 'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm. 		•			
'OK'>Click 'OK'. 11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	10.	**			
11. ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	10.	y ya			
Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.	11.	ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Transient>in the Full			
Click OK?		Transient Options Tick Transient effects and in the Algorithm Field>select HHT algorithm.			
CHEN UN.		Click 'OK'.			

ANSYS Main Menu: Solution >Analysis Type> Sol'n controls >Nonlinear>Click Set Convergence Criteria>Replace>Tolerance about VALUE>0.0001> OK>Close>Close>OK ANSYS Main Menu: Solution > Analysis Type> Sol'n controls > Basic> in the Write Items to 13. Result field, Tick User selected>Nodal DOF solution and in the Frequency field> select Write every Nth Substep, then in the Time Control field >in the Time at end of load step type '0.0002' and Tick No. of Substeps and type 5 in the No. of Substeps field. Click 'OK' ANSYS Main Menu: Solution>Load step options>Output Ctrls> Solu Printout>in the Solu Printout Controls window, in the Item for Printout Control field select 'Basic quantities' and in the Print frequency field, Tick None. Click 'OK'. ANSYS Main Menu: Solution>Load step options>Load step opts>Write LS file> Click 15. ANSYS Main Menu: Solution>Load step options >Output ctrls >Solu printout>>in the **16.** Solu Printout Controls window, in the Item for Printout Control field select 'Basic quantities' and in the Print frequency field, Tick Last Substep. Click 'OK'. ANSYS Main Menu: Solution > Analysis Type> Sol'n controls > Basic> in the Time Control 17. field>in the Time at end of load step type'10' and type 40 in the No. of Substeps field. Click 'OK'. 18. ANSYS Main Menu: Solution>Load step options >Load step opts>Write LS file> Click 'OK' ANSYS Main Menu: Solution>Solve>From LS file, in the Solve Load Step Files, in the 19. LSMIN field, type '1', in the LSMAX field, type '2' and in the LSINC field, type '1'. Click 'OK'. ANSYS Main Menu: Time Hist Postpro >Close the window 20. ANSYS Main Menu: Time Hist Postpro > Settings > Data > in the Data Settings window, in the TMIN field, type '0.003', in the TMAX field, type '10' and in the TINC field, type '1'. Click ANSYS Main Menu: Time Hist Postpro >Define Variable>Add> in the Add Time-History 22. Variable window, Tick Nodal Solution. Click 'OK', then in the Define Nodal Data window, in the NVAR field, type '2', in the NODE field, type '2', and in the User specified Label field, type '2UX'. Then in the Item, Comp Data item, Pick DOF solution (sub window 1) and Translation UX (sub window 2). Click 'OK', ANSYS Main Menu: Time Hist Postpro >Graph Variables>in the Graph Time- History 23. Variable window, in the NVAR1 field, type '2'. Click 'OK', ANSYS main window shows the corresponding output graph. 24. With the above said step, Change the Damping Coefficient (in Step 5) as C = 0 (no damper), 6.32 (under damped), 63.2 (critically damped), and 75.84 (over damped). See the corresponding output graph in the ANSYS main window.

MERITS: 1.time saved 2.achived high accuracy

APPLICATIONS: dynamic analysis of machine elements

RESULT:

Thus the transient analysis of a spring mass damper system has been analyzed.

Ex: No: 10 MODAL ANALYSIS OF A SINGLE DEGREE SPRING MASS SYSTEM USING ANSYS

AIM: Determine the Natural frequency of the spring mass system shown in Fig.6 with spring stiffness (K) = 100 N/m, and mass (m) = 10 kg.

Problem:



Analytical Solution:

$$f_n = \frac{1}{2\pi} \sqrt{\frac{K}{m}} = \frac{1}{2\pi} \sqrt{\frac{100}{10}} = 0.50329 \text{ Hz}$$

ANSYS Analysis Procedure:

- Utility menu bar: select File > Change Title:
 Enter the title (Give title of your choice) in the window appeared and Click 'OK'.
- 2. ANSYS Main Menu: Preferences > Structural>Click 'OK'
- 3. ANSYS Main Menu: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>select Combination (sub window 1)> Spring Damper 14(sub window 2)>Click 'OK'
- 4. In the Element type window, **click 'Options'**, in the element type options window, in the DOF select 1D behavior K2 KEY OPTION field select 'Longitude UY DOF' and then **click 'OK'** and Close
- 5. ANSYS Main Menu: Preprocessor>Element Type > Add/Edit/Delete > in the window click Add>select Structural Mass (sub window 1)>3D mass 21 (sub window 2)>Click 'OK'
- 6. In the Element type window, **click 'Options'**, in the element type options window, in the Rotary Inertia options K3 KEY OPTION field select '2-D w/o rot iner' and then Click 'OK' and Close
- 7. **ANSYS Main Menu: Preprocessor>Real constants>Add>Click Combin14>ok>in the Real Constant Set Number 1, for COMBIN14 window, in the Spring constant K field type '100' and in the Damping coefficient CV1 field, type '10' then Click 'OK'.**
- 8. **Now choose Mass21** in the Real constant window>**Click 'OK'**, in the Real Constant Set Number 2 window, in the Mass field, type Mass = '10', then **Click 'OK'**.
- 9. **ANSYS Main Menu: Preprocessor>Modeling>Create>Nodes>In Active CS>** type the following in the Create Nodes in the Active Coordinate System window

Node number	\mathbf{X}	\mathbf{Y}	${f Z}$
1	0	0	0 (Click Apply)
2	0	-1	0 (Click OK)

- 10. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Element Attributes>In the Element Attributes window, in the Element Type field, select 1 COMBIN14 and in Real Constant Number type field, select '1' and Click 'OK'.
- 11. In the Command window bar, type: E.1.2
- 12. ANSYS Main Menu: Preprocessor>Modeling>Create>Element>Element Attributes>In the Element Attributes window, in the Element Type field, select 2 MASS21 and in Real Constant Number type field, select '2' and Click 'OK'
- 13. In the Command window bar, type: E. 2
- 14. ANSYS Main Menu: Solution >Define Loads > Apply > Structural > Displacement >On nodes>Type node 1 in the Apply U, ROT on Nodes window click 'Apply', then select 'All dof' in the Apply U, ROT on Nodes window (Check Apply as field with 'Constant value' and VALUE = 0), then click 'OK'
- 15. In the Command window bar, type: M.2.UY
- 16. ANSYS Main Menu: Solution > Analysis Type>New Analysis>Modal>Click'OK'.
- 17. ANSYS Main Menu: Solution >Analysis Type>Analysis option >MODOPT set to reduced>No. of Modes to Extract= 1> Click 'OK'.
- 18. ANSYS Main Menu: Solution > Solve > Current LS>Click Solve.
- 19. Click 'Close' in Solution is Done window.
- 20. In the ANSYS output window we can see the Natural Frequency of the system defined.

MERITS: 1.time saved 2.achived high accuracy

APPLICATIONS: • Bin or Hopper Agitation & Unloading

- Trailer Hopper Agitation & Unloading
- Bulk Material Settling & Packing
- Bulk Material Feeding & Conveying
- Bulk Material and Powder Screening & Scalping
- Chute & Pipe Material Flow
- Dust Collector Filter & Precipitator Cleaning

RESULT:

Thus the Natural frequency of the spring mass system has been analyzed and animated

Ex: No: 11. THERMAL STRESS ANALYSIS OF A 2D COMPONENT - STATIC AIM:

To determine the thermal deformations at various points of the 2D components due to the temperature load applied over it.

SOFTWARE:

Ansys 14

PROCEDURE:

- 1. Start \rightarrow Program \rightarrow Ansys \rightarrow Ansys product launcher
- 2. Preference \rightarrow Select Structural and Thermal \rightarrow OK
- 3. Preprocessor \rightarrow Element Type \rightarrow Add \rightarrow Add \rightarrow Coupled field \rightarrow Vector Quad 13 \rightarrow Ok

Option \rightarrow K1= UX UY Temp AZ \rightarrow Ok

4. Material Properties \rightarrow Material Library \rightarrow Import Library \rightarrow SI \rightarrow Ok

Browse \rightarrow C: Program file \rightarrow Ansys INC \rightarrow V140 \rightarrow Ansys \rightarrow Matlib \rightarrow select any one material \rightarrow open \rightarrow Ok \rightarrow close

- 5. Modelling \rightarrow create \rightarrow Area \rightarrow Rectangle \rightarrow By 2 corners \rightarrow Width =10, Height = 10 \rightarrow Ok
- 6. Meshing \rightarrow Mesh Tool \rightarrow Global, Set = 0.5 \rightarrow Ok

Mesh \rightarrow select the object \rightarrow Ok

- 7. Solution \rightarrow Define load \rightarrow Apply \rightarrow Structural \rightarrow Displacement \rightarrow Onlines \rightarrow Select the Base line \rightarrow DOF \rightarrow Ok
- 8. Solution \rightarrow Define load \rightarrow Apply \rightarrow Thermal \rightarrow Temperature \rightarrow on lines \rightarrow Select left side line \rightarrow Temp = 40° \rightarrow Apply \rightarrow Select Right side line \rightarrow Temp = 120° \rightarrow Ok
- 9. Solve \rightarrow Current LS \rightarrow Ok
- 10. General postprocessor \rightarrow Plot Result \rightarrow Contour Plot \rightarrow Nodal Solution \rightarrow Select

Temperature or Stress \rightarrow Ok

MERITS: 1.time saved 2.achived high accuracy

APPLICATIONS: .heat exchangers

2.air cooling and water cooling engines

RESULT:

Thus the thermal deformation over a 2D component is analyzed, animated and plotted.

Ex: No: 12. CONDUCTIVE HEAT TRANSFER ANALYSIS OF A 2D COMPONENT AIM:

To determine the conductive heat transfer of a 2D component

SOFTWARE:

Ansys 14

PROCEDURE:

- 1. Start \rightarrow Program \rightarrow Ansys \rightarrow Ansys product launcher
- 2. Preference \rightarrow Thermal \rightarrow OK
- 3. Preprocessor \rightarrow Element Type \rightarrow Add \rightarrow Add \rightarrow Solid \rightarrow Quad 4 node 55 \rightarrow Ok
- 4. Material Properties → Material Library → Import Library → SI (MKS) → Ok

Browse \rightarrow C: Program file \rightarrow Ansys INC \rightarrow V140 \rightarrow Ansys \rightarrow Matlib \rightarrow select any one material \rightarrow open \rightarrow Ok \rightarrow close

- 5. Modelling \rightarrow create \rightarrow Area \rightarrow Rectangle \rightarrow By 2 corners \rightarrow Width =100, Height = 100 \rightarrow Ok
- 6. Meshing \rightarrow Mesh Tool \rightarrow Global , Set \rightarrow Element type = $10 \rightarrow$ Click small size \rightarrow Mesh \rightarrow Select the object \rightarrow Ok
- 7. Solution \rightarrow Define load \rightarrow Apply \rightarrow Thermal \rightarrow Temperature \rightarrow On lines \rightarrow Select the left line \rightarrow Temp Value = 40° \rightarrow Apply \rightarrow select the right side line \rightarrow Temp value = 120° \rightarrow Ok
- 8. Solve \rightarrow Current LS \rightarrow Ok
- 9. General postprocessor \rightarrow Plot Result \rightarrow Contour Plot \rightarrow Nodal Solution \rightarrow DOF Solution \rightarrow Nodal Temp \rightarrow Ok

To check the Temperature at various point:

Query Result \rightarrow Sub grid solution \rightarrow DOF solution \rightarrow Temperature \rightarrow Ok \rightarrow click any point on the object Temperature value displayed on the screen

MERITS: 1.time saved 2.achived high accuracy

APPLICATIONS: .heat exchangers

2.air cooling and water cooling engines

RESULT:

Thus the heat conduction over a 2D component is analyzed, animated and plotted.

Ex: No: 13.CONVECTIVE HEAT TRANSFER ANALYSIS OF A 2D COMPONENT AIM.

To determine the convective heat transfer analysis of a 2D component

SOFTWARE:

Ansys 10.0

PROCEDURE:

- 1. Start \rightarrow Program \rightarrow Ansys \rightarrow Ansys product launcher
- 2. Preference \rightarrow Thermal \rightarrow OK
- 3. Preprocessor \rightarrow Element Type \rightarrow Add \rightarrow Add \rightarrow Solid \rightarrow Quad 4 node 55 \rightarrow Ok
- 4. Material Properties → Material Library → Import Library → SI (MKS) → Ok

Browse \rightarrow C: Program file \rightarrow Ansys INC \rightarrow V140 \rightarrow Ansys \rightarrow Matlib \rightarrow select any one material \rightarrow open \rightarrow Ok \rightarrow close

- 5. Modelling \rightarrow create \rightarrow Area \rightarrow Rectangle \rightarrow By 2 corners \rightarrow Width =100, Height = 100 \rightarrow Ok
- 6. Meshing \rightarrow Mesh Tool \rightarrow Global , Set \rightarrow Element type = $10 \rightarrow$ Click small size \rightarrow Mesh \rightarrow Select the object \rightarrow Ok
- 7. Solution \rightarrow Define load \rightarrow Apply \rightarrow Thermal \rightarrow Temperature \rightarrow On lines \rightarrow Select the left line \rightarrow Temp Value = 40° \rightarrow Apply \rightarrow select the right side line \rightarrow Temp value = 120° \rightarrow Ok
- 8. Solution \rightarrow Define Load \rightarrow Apply \rightarrow Convection \rightarrow on lines \rightarrow Film coefficient = 20, Bulk Temp = $20^{\circ} \rightarrow Ok$
- 9. Solve \rightarrow Current LS \rightarrow Ok

10. General postprocessor \rightarrow Plot Result \rightarrow Contour Plot \rightarrow Nodal Solution \rightarrow DOF Solution \rightarrow Nodal Temp \rightarrow Ok

To check the Temperature at various point:

Query Result \rightarrow Subgrid solution \rightarrow DOF solution \rightarrow Temperature \rightarrow Ok \rightarrow click any point on the object Temperature value displayed on the screen

MERITS: 1.time saved 2.achived high accuracy

APPLICATIONS: 1. heat exchangers

2.air cooling and water cooling engines

RESULT: Thus the heat convective over a 2D component is analyzed, animated and plotted.

STUDY OF MATLAB

AIM:

To study the mathematical computing simulation methods using MATLAB

MATLAB

MATLAB integrates mathematical computing, visualization, and a powerful language to provide a flexible environment for technical computing. MATLAB includes tools for: Data acquisition

- ✓ Data analysis and exploration
- ✓ Visualization and image processing
- ✓ Algorithm prototyping and development
- ✓ Modeling and simulation
- ✓ Programming and application development

Category	Description
Desktop environment	The MATLAB desktop is a graphical user interface that transforms MATLAB in to an integrated environment for exploration and development

Graphics	illustrating curve, fitting, solving differential equations, and fast Fourier transform (FFT) These demos illustrate graphics functions that
	create 2-D and 3-D plots of data, and introduce visualization techniques. See also MATLAB
Language	MATLAB is both an environment and a programming language that allows you to build your own reusable tools. You can write programs as either scripts or functions using data types, operators, expressions, and statements that are similar to programming languages such as "C". You can also create
	object-oriented classes and objects in MATLAB or use its built- in Java interface to create and work with Java classes and objects.
Automation Client Interface (COM)	MATLAB provides an interface that enables communication with Automation servers and Automation controls. The demos in this section illustrate some of the features of this interface.

Features	Simulink provides many features for powerful and intuitive modeling. Some major features are illustrated in these demonstration models.
General	Simulink has the ability to simulate a large range of systems, from very simple to extraordinarily complex. The models and demonstrations that you will see in this section include both simple and complex systems. Although the complex systems are nowhere near the limits of what can be done, they hint at the level of sophistication that you can expect.
Automotive	Simulink, stateflow and the Real-Time workshop represent the industry standard toolset in the automotive field. The models that you will see in this area showcase the use of Math works tools in various automotive applications.
Aerospace	Simulink, statflow and the Real-Time Workshop represent the industry standard toolset in the aerospace field. The models that you will see in this area showcase the use of Math Works tools in various aerospace applications.
Real-Time Workshop	Generate C code from Simulink models

SimMechanics	Model and simulate mechanical systems
Simpower systems	Model and simulate electrical power systems
Simulink Report Generator	Automatically generate documentation for Simulink and stateflow models
State flow	Design and simulate event-driven system
XPC Target	Perform real-time rapid prototype using PC hardware

RESULT:

Thus the basics of MATLAB are studied.
